


Space Launch Delta 45 Hazard Area



SPACEX STARLINK 4-3

02 Dec 21

LAUNCH HAZARD AREA COORDINATES

(PURPLE BOX ON MAP)

2837 12.93N 8036 16.14W

2912N 7953W

2907N 7949W

2835N 8022W

2829 10.43N 8032 24.37W

Please remain clear of the

Launch Hazard Area from:

2:45 PM – 7:45 PM

If launch is delayed the next attempt will be **03 Dec 21**.

Backup Launch Hazard Area Times:

2:30 PM – 7:30 PM

Launch Information Recorded Line:

1-800-470-7232

Detailed Launch Area Information can be obtained using Coast Guard channel 16 or FM81A and Notice to Mariners @ <http://www.navcen.uscg.gov/?pageName=lnmDistrict®ion=7>